



CANADIAN MILL SERVICES ASSOCIATION

WOOD TREATMENT And PRESERVATION-SITE INSPECTION REPORT

COMPANY: Koppers Inc. Treatment Specification: CSA- 080 Species: Douglas Fir

LOCATION: Ashcroft, B.C.

Charge: 3632 Destination: Lacombe, Alberta DATE: November 18,2022

Penetration Results (in mm)-

Penetration Depth	Sapwood %	Penetration Depth	Sapwood %
1 16mm(4")	100	15 15mm	100
2 17mm	100	16 11mm(3")	100
3 11mm(3")	100	17 9mm	100
4 13(4")	100	18 19mm	100
5 20mm	100	19 25mm	100
6 16mm	100	20 8mm	100
7 15mm	100	21 14mm	100
8 12mm(3")	100	22 23mm	100
9 12mm(4")	100	23 20mm	100
10 16mm	100	24 19mm	100
11 22mm	100	25 11mm	100
12 18mm	100	26 17mm	100
13 15mm(4")	100	27 17mm	100
14 17mm	100	28 25mm	100

PENETRATION RESULTS:	
PASS	<input checked="" type="checkbox"/>
FAIL	<input type="checkbox"/>

Incising (Lumber)

Good	Fair	Poor
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Retention by Gauge

Required: 6.0 pcf Retained 8.14

Preservative used: Creosote

Tank Begin Gallons: 40493 Tank End Gallons: 39538

Treatment Method: Lowry

Treatable Cubic Feet in Charge: 32,226

Comments

All pieces from originally graded tally accepted. Graded and marked/grade stamped.

Supervisor: Kristopher Reklinski