



# CANADIAN MILL SERVICES ASSOCIATION

## WOOD TREATMENT And PRESERVATION-SITE INSPECTION REPORT

COMPANY: Koppers Inc. Treatment Specification: CSA- 080 Species: Douglas Fir

LOCATION: Ashcroft, B.C.

Charge: 3634 Destination: Lacombe, Alberta DATE: November 18,2022

### Penetration Results (in mm)-

Penetration Depth	Sapwood %	Penetration Depth	Sapwood %
1 15mm	100	15 16mm	100
2 19mm	100	16 13mm	100
3 12mm(3")	100	17 10mm(3")	100
4 16mm(4")	100	18 19mm	100
5 14mm	100	19 17mm	100
6 22mm	100	20 8mm	100
7 18mm	100	21 16mm	100
8 10mm(3")	100	22 25mm	100
9 10mm(3")	100	23 19mm	100
10 15mm	100	24 24mm	100
11 24mm	100	25 15mm	100
12 18mm	100	26 14mm	100
13 9mm	100	27 18mm	100
14 14mm	100	28 21mm	100

<b>PENETRATION RESULTS:</b>	
PASS	<input checked="" type="checkbox"/>
FAIL	<input type="checkbox"/>

### Incising (Lumber)

Good	Fair	Poor
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### Retention by Gauge

Required: 6.0 pcf Retained 9.47

Preservative used: Creosote

Tank Begin Gallons: 47574 Tank End Gallons: 47071

Treatment Method: Lowry

Treatable Cubic Feet in Charge: 31,513

### Comments

All pieces from originally graded tally accepted. Graded and marked/grade stamped.

Supervisor: Kristopher Reklinski