

Stella Jones

1111 Pacific Street, Prince George, British Columbia V2N 5S4 phone 250-561-1161 fax 250-561-0903

Plant: PC Date Tracked: 15/04/19 Customer: Cooper-Fellow
 Charge #: 74919 Species: FIR Dimensions: _____
 Commodity: Timbers
 Standard Tracked For: CS4080-8
 Penetration Requirements: _____

6x12x24 (28)
 4x12x26 (32)
 12x14x20 (12)
 4x12x24 (8)
 4x12x18 (36)

C500

| Core # | Penetration - 1/4" mm | Squared - 1/4" mm | Conformance % |
|--------|-----------------------|-------------------|---------------|
| 1 | 14 | | |
| 2 | 13 | | |
| 3 | 13 | | |
| 4 | 17 | | |
| 5 | 13 | | |
| 6 | 13 | | |
| 7 | 10 | | |
| 8 | 14 | | |
| 9 | 17 | | |
| 10 | 13 | | |
| 11 | 13 | | |
| 12 | 15 | | |
| 13 | 23 | | |
| 14 | 13 | | |
| 15 | 13 | | |
| 16 | 15 | | |
| 17 | 13 | | |
| 18 | 20 | | |
| 19 | 13 | | |
| 20 | 14 | | |

| Core # | Penetration - 1/4" mm | Squared - 1/4" mm | Conformance % |
|--------|-----------------------|-------------------|---------------|
| 21 | | | |
| 22 | | | |
| 23 | | | |
| 24 | | | |
| 25 | | | |
| 26 | | | |
| 27 | | | |
| 28 | | | |
| 29 | | | |
| 30 | | | |
| 31 | | | |
| 32 | | | |
| 33 | | | |
| 34 | | | |
| 35 | | | |
| 36 | | | |
| 37 | | | |
| 38 | | | |
| 39 | | | |
| 40 | | | |

Penetration Minimum: 10 mm
 Squared Minimum: 10 mm
 % Conformance: _____
 Date Assessed: April 16, 2018

Penetration Maximum: 23 mm
 Squared Maximum: 23 mm
 Average Penetration: 14.45 mm.
 Assessed By: W. [Signature]

Comments: _____

Average % _____ Loss _____ High _____

Stella-JoneS

7177 Pacific Street, Prince George, BC V2N 5S4

Phone: (250) 561-1161

Certificate of Treatment

This is to certify that the material described below has been pressure treated to the requirements of CSA Standards and the Best Management Practices.

Customer Name: *Goodfellow inc.*
 Address *225, RUE Goodfellow*
Delson QC. J5B 1V5
 Contact:
 Customer's Order #: *494174*
 SJI Order#: *18190*
 Commodity: *Timbers.*
 Species: *FIR.*

| Quantity | Dimensions | Length (in feet) |
|-----------|-------------|------------------|
| <i>12</i> | <i>4x12</i> | <i>18</i> |
| <i>24</i> | <i>3x12</i> | <i>18</i> |
| <i>24</i> | <i>3x10</i> | <i>18</i> |
| <i>48</i> | <i>4x12</i> | <i>26</i> |
| <i>40</i> | <i>4x12</i> | <i>24</i> |
| <i>16</i> | <i>6x12</i> | <i>26</i> |
| <i>16</i> | <i>6x12</i> | <i>24</i> |
| | | |
| | | |
| | | |

Treating Plant: *SJI Prince George*
 Preservative: *CNEO*
 Charge #: *74917*
 Net Retention: *8.73 pcf by guage*
 Shipping Plant: *SJI Prince George*
 Date of Issuance: *may, 3, 2019*

Norm Wood
 Quality Control Co-ordinator

Norm Wood

Ryan Booth
 Plant Manager

Ryan Booth

Stella Jones

7177 Pacific Street, Prince George, British Columbia V2N 5S4 phone 250-561-1161 fax 250-561-0902

Plant: PG Date Treated: 12/04/19 Customer: Goodfellow
 Charge #: 74917 Species: FIR Diameter: _____
 Commodity: Timbers
 Standard Treated To: CS19080-X
 Penetration Requirements: _____

CREO

4x12x18 (12)
 3x12x18 (24)
 3x10x18 (24)
 4x12x26 (48)
 4x12x24 (40)
 6x12x26 (16)
 6x12x24 (16)

| Core # | Penetration - 1/ | mm | Sapwood - 1/ | mm | Conformance % |
|--------|------------------|----|--------------|----|---------------|
| 1 | 14 | | | | |
| 2 | 22 | | | | |
| 3 | 13 | | | | |
| 4 | 14 | | | | |
| 5 | 16 | | | | |
| 6 | 15 | | | | |
| 7 | 12 | | | | |
| 8 | 16 | | | | |
| 9 | 14 | | | | |
| 10 | 12 | | | | |
| 11 | 13 | | | | |
| 12 | 12 | | | | |
| 13 | 14 | | | | |
| 14 | 13 | | | | |
| 15 | 14 | | | | |
| 16 | 15 | | | | |
| 17 | 21 | | | | |
| 18 | 16 | | | | |
| 19 | 15 | | | | |
| 20 | 12 | | | | |

| Core # | Penetration - 1/ | mm | Sapwood - 1/ | mm | Conformance % |
|--------|------------------|----|--------------|----|---------------|
| 21 | | | | | |
| 22 | | | | | |
| 23 | | | | | |
| 24 | | | | | |
| 25 | | | | | |
| 26 | | | | | |
| 27 | | | | | |
| 28 | | | | | |
| 29 | | | | | |
| 30 | | | | | |
| 31 | | | | | |
| 32 | | | | | |
| 33 | | | | | |
| 34 | | | | | |
| 35 | | | | | |
| 36 | | | | | |
| 37 | | | | | |
| 38 | | | | | |
| 39 | | | | | |
| 40 | | | | | |

Penetration Minimum: 12 mm
 Sapwood Minimum: 12 mm

Penetration Minimum: 22 mm
 Sapwood Minimum: 22 mm
 Average Penetration: 14.65 mm.
 Inspected By: M. Jones Jones

% Conformance: _____
 Date Assessed: April 16 2019

Comments: _____

14/CS: ~ _____
 Average % _____
 Lot# _____
 Sig: _____

Stella-Jones

1117 Pacific Street, Prince George, British Columbia V2N 5S4 phone 250-561-1161 fax 250-561-0902

Plant: PCs Date Treated: 10/04/19 Customer: Goodfellow
 Charge #: 74922 Species: FIRE Dimension: 12x14x28 (12)
 Commodity: Timbers
 Standard Treated To: CS4080-8 CREO
 Penetration Requirements: _____

| Core # | Penetration - 1/ | mm | Separation - 1/ | mm | Conformance % |
|--------|------------------|----|-----------------|----|---------------|
| 1 | 13 | | | | |
| 2 | 13 | | | | |
| 3 | 13 | | | | |
| 4 | 13 | | | | |
| 5 | 13 | | | | |
| 6 | 13 | | | | |
| 7 | 14 | | | | |
| 8 | 14 | | | | |
| 9 | 14 | | | | |
| 10 | 13 | | | | |
| 11 | 14 | | | | |
| 12 | 14 | | | | |
| 13 | 13 | | | | |
| 14 | 13 | | | | |
| 15 | 13 | | | | |
| 16 | 14 | | | | |
| 17 | 13 | | | | |
| 18 | 14 | | | | |
| 19 | 20 | | | | |
| 20 | 16 | | | | |

| Core # | Penetration - 1/ | mm | Separation - 1/ | mm | Conformance % |
|--------|------------------|----|-----------------|----|---------------|
| 21 | | | | | |
| 22 | | | | | |
| 23 | | | | | |
| 24 | | | | | |
| 25 | | | | | |
| 26 | | | | | |
| 27 | | | | | |
| 28 | | | | | |
| 29 | | | | | |
| 30 | | | | | |
| 31 | | | | | |
| 32 | | | | | |
| 33 | | | | | |
| 34 | | | | | |
| 35 | | | | | |
| 36 | | | | | |
| 37 | | | | | |
| 38 | | | | | |
| 39 | | | | | |
| 40 | | | | | |

Penetration Minimum: 10 mm

Separation Minimum: 10 mm

% Conformance: _____

Date Assessed: April 18 2019

Comments: _____

MJC: _____

Assessed By: _____

Lot: _____

Fig: _____

Penetration Minimum: 20 mm

Separation Minimum: 20 mm

Average Penetration: _____

Assessed By: A Brownwood